

Site 31/32

Survey No. WA-III-100

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic Frame house Demolished?

and/or common

2. Location

JKC
12/105

street & number north side of Sandy Hook Road, .1 mile west of Clark Road not for publication

city, town Sandy Hook _____ vicinity of _____ congressional district sixth

state Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military
			<input type="checkbox"/> museum
			<input type="checkbox"/> park
			<input type="checkbox"/> private residence
			<input type="checkbox"/> religious
			<input type="checkbox"/> scientific
			<input type="checkbox"/> transportation
			<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name _____

street & number _____ telephone no.: _____

city, town _____ state and zip code _____

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber _____

street & number Washington Street folio _____

city, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title _____

date _____ federal state county local

depository for survey records _____

city, town _____ state _____

7. Description

Survey No. WA-III-100

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a L-shape plan. It has a four-bay by two-bay main section with a two-bay ell. The main facade has a full-length, one-story porch. The house is constructed on a sloped bank so that the foundation level is a full-story level on the main facade. The porch is supported by brick piers covered in lattice-work. The frame structure is covered in a diamond-shaped asphalt siding. The main facade has an entrance in the second bay from the west, two-over-two sash windows in the other bays on the first and second story, and a bracket cornice. The structure appears to date from the mid-19th century.

The property is located on the north side of Sandy Hook Road, approximately .1 mile west of Clark Road, in Sandy Hook. The site is terraced with a brick retaining wall in the front yard and another two stone retaining walls along the side and at the rear of the house. The main facade faces south.

The two-story structure is constructed of frame covered in a diamond-shaped asphalt siding. The stone foundation rises a full story in the front of the house. This full story is enclosed by the brick piers and lattice-work at the foundation level of the front porch. The first story of the front porch has square posts with a paneled railing. The entrance is located in the second bay from the west. Two-over-two sash windows are located in the other bays of the main facade on the first story and in the four bays on the second story. The windows are located in the two bays on each story of each gable end. There is a bracket cornice on the front of the house. The gable roof is covered in sheet metal and has an interior-end brick chimney at the east gable end. The west gable end is where the ell meets the house and has a side entrance. A single window is on the first and second floors of the west gable end.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-III-100

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook Survey District.


WA-III-100

Frame House

(site?)

Sandy Hook Road (MD 180), Sandy Hook

Harpers Ferry Quadrangle



1993-94 Aerial Photo




FREDERICK & WASHINGTON

HARPERS FERRY, VA-MD-W VA
QUADRANGLE
USGS 7.5 minute map
1:24 000
1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST

767 768 (KEEDYSVILLE) 769





1. WA-III-100
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1